

USE

- 1 Inspect the equipment daily and replace any damaged parts before use. This is particularly important if different workers are using the same jack.
- 2 Make a directional cut (a) in the tree.
- 3 Bring the arm with the claw approx. 50 cms (20") out of the telescopic tube. Place the spindle peg into one of the stop holes and fix the locking (b).
- 4 Check that the ground under foot is stable. If not, place a thick wooden board underneath the jack. (c).
- 5 Position the jack against the tree at an angle of about 25° - 35° behind the direction of the cut (d). Turn the handle to bring the tool under pressure i. e. until the claw is firmly fixed into the trunk and the foot is solidly anchored into the ground.
- 6 Make the felling cut (e) leaving 3 – 5 cm at the break points (f). Turn the hand lever several times to try to topple the tree. It may be necessary to deepen the felling cut to ease this operation.
- 7 After use the telescopic arm is returned into the foot by hand whilst turning the lever with the other hand.




Fig.3